

TRACKSTER

SERVICE BULLETIN

Service Dept. CUSHMAN MOTORS Lincoln, Nebraska



14

PARKING BRAKE

A grease fitting has been added to the parking brake pivot shaft housing to provide a means of lubrication.

All Trackster vehicles shipped from the factory after July 15, 1972 have a grease fitting located on the backside of the pivot shaft housing.

A parking brake with a grease fitting should be lubricated every three months with a grease gun and lithium-base grease.

All Trackster vehicles not equipped with a grease fitting can be modified by purchasing a new "Bracket with Shoe," Part No. 882371, for replacement.