

TRACKSTER

SERVICE BULLETIN

Service Dept. CUSHMAN MOTORS Lincoln, Nebraska



15

PISTON SET

PART NO. 883025

Improved pistons, pins and retainers are now available for service replacement parts for the Trackster engines. The new piston and related parts will be furnished individually or as a set. The set will consist of the following parts:

<u>Part No.</u>	<u>Description</u>	<u>Quantity</u>
162148	Piston #1 cylinder - right side	1
162169	Piston #2 cylinder - left side	1
114161	Wrist pin	2
316968	Retaining ring	4
162279	Ring set	2

The following parts have been discontinued:

113835	Wrist pin
302577	Retaining ring
161810	Ring set
161999	Piston

Part Nos. 113835, 302577 and 161810 will be cancelled from all future orders. If the old piston, Part No. 161999, is ordered, we will substitute a set, Part No. 883025, for each piston ordered.

If rings are needed for an engine with 161999 pistons (three-ring piston), order three Part No. 162279 ring set. This ring set consists of two rings per set.

Two tools, Part No. 317829, driver, and Part No. 317830, cone, will facilitate installation of the piston pin retainers.