

TRACKSTER

SERVICE BULLETIN

Service Dept. CUSHMAN MOTORS Lincoln, Nebraska



17

FLOTATION MODEL TRACKSTER

SAFETY WARNING

When operating a Flotation Model Trackster on ice, care must be taken to insure that with the addition of any accessories or modifications, the vehicle must also have additional flotation to compensate for the added weight in the event the vehicle breaks through the ice.

Tests have shown that the Flotation Model Trackster with no accessories or modifications will float full of water with two people sitting on the seat. The two people will be in water to their waists. The buoyancy of the vehicle is easily affected when floating full of water by additional weight not having the same density as water; however, payloads with approximately the same density as water, i.e., gas, oil, will have little effect.

Alert users in your area to be aware of this possible safety hazard.