

TRACKSTER

SERVICE BULLETIN

Service Dept. CUSHMAN MOTORS Lincoln, Nebraska



19

REPLACEMENT

CHOKE AND LIGHT SWITCH

A new choke cable assembly, Part No. 882655, is available for replacement. The new choke cable assembly incorporates a wiper to help prevent moisture from entering the assembly.

A new light switch, Part No. 882654, is available for replacement. This switch has an O-ring for moisture exclusion.

The original part numbers should not be used; namely, Part No. 819538, choke, and Part No. 806774, switch.