

# TRACKSTER

## SERVICE BULLETIN

Service Dept. CUSHMAN MOTORS Lincoln, Nebraska



24

### CYLINDER STUD NUTS

PART NO. 114232

It is imperative that anytime the cylinder stud nuts are removed from a Trackster engine (i.e., during engine rebuilding), the cylinder stud nuts be replaced with new nuts, Part No. 114232.

We suggest you order and stock an ample supply of these nuts.