## 22

## TRACKSTER SERVICE BULLETIN

Service Dept. CUSHMAN MOTORS Lincoln, Nebraska

## REPLACEMENT ENGINE

PART NO. 883168

A replacement engine (29 H.P.) is available for use in all Trackster vehicles. No modification is necessary for installation.

The replacement engine consists of a short block plus intake manifold, reed plate assembly, rear fan housing assembly, armature plate assembly and flywheel assembly. Gaskets are also included.

Replacement engine cost should be considered when major engine repair is necessary.

Refer to the Parts Price Supplement for prices.

15C-6-73-CG TB-22